
Comfort-Aire®


Century®

REPLACEMENT PARTS LIST

**Dual Zone Low Temperature
Ductless Mini-Split**

A-VMH18DU-1

EXPLODED VIEW



REPLACEMENT PARTS

| Location | Part Name | Quantity | Part No. |
|----------|--|----------|----------------|
| 1 | Rear net | 1 | 12222000006604 |
| 2 | Condenser assembly | 1 | 15822000002068 |
| 3 | Pipe Temperature Sensor | 1 | 11201007000136 |
| 3 | Indoor Coil Outlet Pipe Temp Sensor Assy | 1 | 11201007000259 |
| 4 | Rear right clapboard assembly | 1 | 12222300000510 |
| 5 | Big handle | 1 | 12222300000529 |
| 6 | Water collector | 1 | 12122300000110 |
| 7 | Front right clapboard assembly | 1 | 12222500A00135 |
| 8 | Valve plate | 1 | 12222000005282 |
| 9 | Chassis assembly | 1 | 12222000005267 |
| 10 | Front panel | 1 | 12222000A01431 |
| 11 | Air outlet grille | 1 | 12222000007904 |
| 12 | Axial flow fan | 1 | 12100105000084 |
| 13 | Brushless DC Motor | 1 | 11002015000247 |
| 14 | Supporter subassembly of fan motor | 1 | 12222000005162 |
| 15 | Left side plate assembly of cabinet | 1 | 12222000006665 |
| 16 | Partition board assembly | 1 | 12222200001156 |
| 17 | Room Temperature Sensor | 1 | 11201007000039 |
| 18 | Top cover assembly | 1 | 12222500000587 |
| 19 | Electronic control box subassembly | 1 | 17222300A01927 |
| 19.1 | Cover of electronic control box | 1 | 12122000006905 |
| 19.2 | Main control board subassembly | 1 | 17122300A01917 |
| 19.4 | Electronic installing box | 1 | 12122300000170 |
| 19.7 | Inverter control board subassembly | 1 | 17122000A16230 |
| 19.7.1 | Radiator | 1 | 11203803000677 |
| 20 | Terminal board subassembly | 1 | 17222000A31351 |
| 20.1 | Wire joint | 2 | 17400401000135 |
| 20.2 | Terminal board | 1 | 12222300000033 |
| 20.3 | Terminal board | 1 | 12222300000032 |
| 21 | 4-way Valve Assembly | 1 | 15422300000604 |
| 21.1 | 4-way valve | 1 | 15500216000361 |
| 21.2 | Gas valve | 1 | 15500204000049 |
| 21.4 | Muffler | 1 | 15500506000007 |
| 22 | Liquid valve Assembly | 1 | 15422000A01491 |
| 22.1 | Liquid valve | 2 | 15500208000028 |
| 22.2 | Electronic expansion valve subassembly | 2 | 15500213000046 |
| 23 | Liquid valve assembly | 1 | 15422300000405 |
| 23.1 | Liquid valve | 1 | 15500208000047 |
| 24 | Copper nut | 3 | 15500406000010 |
| 24 | Copper nut | 3 | 15500406000012 |
| 24 | Copper nut | 3 | 15500406000016 |
| 26 | DC Inverter Rotary Compressor | 1 | 11103020000179 |
| 27 | Reactor | 1 | 17400306000058 |
| 27 | Reactor | 1 | 17400306000070 |
| 29 | Discharge Temperature Sensor | 1 | 11201007000246 |
| 30 | Electric heating tube | 1 | 17402002000043 |
| 31 | NA | 1 | 17402001000119 |
| 33 | Low Pressure Valve assembly | 1 | 15422000A01487 |
| 33.1 | Gas valve | 2 | 15500204000021 |
| 34 | Suction pipe | 1 | 15122300001047 |
| 39 | Accumulator cylinder | 1 | 15500508000315 |
| 41 | Drain pipe | 1 | 12100509000059 |
| 43 | accessory | 3 | 15500307000001 |
| 99 | Compressor wire subassembly | 1 | 17401203000939 |

Due to ongoing product improvements, specifications and dimensions are subject to change and correction without notice or incurring obligations. Determining the application and suitability for use of any product is the responsibility of the installer. Additionally, the installer is responsible for verifying dimensional data on the actual product prior to beginning any installation preparations.

Incentive and rebate programs have precise requirements as to product performance and certification. All products meet applicable regulations in effect on date of manufacture; however, certifications are not necessarily granted for the life of a product. Therefore, it is the responsibility of the applicant to determine whether a specific model qualifies for these incentive/rebate programs.

Comfort-Aire. **Century**